

CARTE DE LA ZONE INDUSTRIELLE DE NGAOUNDERE




TABLEAU DES COORDONNEES GAUSS

B27	1337929.923	1811899.284
B29	1337812.84	1811774.59
ZINDR01	1337796.89681438	1811752.11278087
ZINDR02	1337564.87479757	1812062.33776096
ZINDR03	1337454.41161249	1812229.68505787
ZINDR04	1337434.90737236	1812383.26538697
ZINDR05	1337534.36295829	1812657.06324901
ZINDR06	1337621.69764165	1812860.49099413
ZINDR07	1337769.89284603	1813246.70435512
ZINDR08	1337891.48548627	1813537.85936236
ZINDR09	1338040.63309394	1813929.56048319
ZINDR10	1338162.03653305	1814230.55624931
ZINDR11	1338423.45419077	1814843.58404789
ZINDR12	1338599.07690263	1814517.42109558
ZINDR13	1338775.61395977	1814216.51016779